



Consent Agenda Item 9-j

Recommendation for the post approval of the parts and repair work to bus #41 to Cummins Rocky Mountain Sales and Service in the amount of \$15,453.95. This amount includes \$10,317.34 for parts, \$5,486.00 for labor, and a diagnostic charge of \$260.00. There will be a core parts credit of \$609.39. Cummins has provided a two year/100,000-mile warranty on all work. The repair work was needed due to ring failure, EGR cooler failure and injector erosion. The repair work is proprietary due to internal engine work being conducted that required the engine to be disassembled to a point that allowed for the mechanic to determine the exact cause of the issue.