

School Building	Drinking Water Outlets Sampled	Locations which Exceed EPA and/or DOH Action Levels	Remediation Status
Lincoln Orens Middle School	28	<p><u>Exceed EPA 20ppb AL</u> Map location 4: Fountain in classroom 160 Map location 7: Fountain in classroom 153 Map location 8: Fountain in classroom 152 Map location 11: Faucet in home economics classroom 129</p> <p><u>Exceed DOH 15ppb AL</u> Map location 2: Fountain in classroom 162 Map location 9: Fountain in classroom 156</p>	<p>Terminated & Removed Terminated & Removed Terminated & Removed Replaced, Retested, & >15ppb (Aug 30)</p> <p>Terminated & Removed Terminated & Removed</p>
Island Park Public Library	6	NONE	N/A
Hegarty Elementary School	40	<p><u>Exceed EPA 20ppb AL</u> Map Location 18: Fountain in Room 110 Map Location 22: Fountain in Room 107 Map Location 26: Faucet in Kitchen-North Sink</p> <p><u>Exceed DOH 15ppb AL</u> Map Location 9: Water Cooler in Hallway by Room 210A Map Location 19: Water Cooler in Hallway by Room 109</p> <p>Service Connector (non-potable)</p>	<p>Terminated & Removed Replaced, Retested & Passed (Aug 30) Replaced, Retested & Passed (Aug 30)</p> <p>Retest Results Pending Retest Results Pending Retest Results Pending</p>
Island Park Admin	3	NONE	N/A