

Eventus Construction Company Inc.

Cemco Water & Wastewater Specialists Inc.

District: Carmel Central School District

Location: Matthew Patterson Elementary School

Recorded By:

51-100 Cody

KEY:

Type of Outlet:	WF= Water Fountain
NO= Nurse Office	KS= Kitchen Sink
FL= Faculty Lounge	CS= Classroom Sink
BO= Boiler Room	OS= Outside Spigot
RR= Restroom Sink	EW= Eye Wash
SS= Slop Sink	FS= Floor Sink
IS= Indoor Spigot	DW= Dish Washer
E= Exceed Allowable Limit	

Draw:	
Date:	9/17/2016
Time:	8: 19AM- 10:00AM

Sample ID	Location	Type of Outlet	Lead Concentration	Notes Required	E
MPES- 001	Outside Main Entrance	OS	0.063		E
MPES- 002	Outside Rm 115	OS	1.22		E
MPES- 003	Outside Rms 122 & 125	OS	0.097		E
MPES- 004	Outside Rm 130	OS	0.051		E
MPES- 005		OS	Does Not Work		
MPES- 006	Outside Gym	OS	0.105		E
MPES- 007	Outside Rm 157	OS	0.606		E
MPES- 008		OS	Does Not Work		
MPES- 009		OS	Does Not Work		
MPES- 010	Outside Rm 184	OS	0.105		E
MPES- 011	Outside Rm 187	OS	0.228		E
MPES- 012	Classroom 122	WF	0.001		

MPES- 013	Classroom 122	CS	0.003		
MPES- 014	Classroom 125	CS	0.004		
MPES- 015	Classroom 125	WF	0.002		
MPES- 016	Classroom 126	CS	0.002		
MPES- 017	Classroom 126	WF	0.002		
MPES- 018	Classroom 126	RR	0.003		
MPES- 019	Classroom 125	RR	0.003		
MPES- 020	Classroom 122	RR	0.002		
MPES- 021	Custodial Closet Rm 119	SS	0.006		
MPES- 022	Classroom 128	CS	0.009		
MPES- 023	Classroom 128	WF	0.001		
MPES- 024	Classroom 128	RR	0.005		
MPES- 025	Classroom 117	CS	0.004		
MPES- 026	Classroom 117	WF	0.002		
MPES- 027	Classroom 117	RR	0.002		
MPES- 028	Classroom 130	CS	0.006		
MPES- 029	Classroom 130	WF	0.002		
MPES- 030	Classroom 130	RR	0.005		
MPES- 031	Classroom 116	CS	0.010		
MPES- 032	Classroom 116	WF	< 0.001		
MPES- 033	Classroom 116	RR	0.005		
MPES- 034	Classroom 132	CS	0.001		

MPES- 035	Classroom 132	WF	0.011		
MPES- 036	Classroom 132	RR	0.005		
MPES- 037	Classroom 112	CS	0.019		E
MPES- 038	Classroom 112	WF	0.002		
MPES- 039	Classroom 112	RR	0.005		
MPES- 040	Classroom 134	CS	0.004		
MPES- 041	Classroom 134	WF	< 0.001		
MPES- 042	Classroom 134	RR	0.003		
MPES- 043	Classroom 110	CS	0.005		
MPES- 044	Classroom 110	WF	< 0.001		
MPES- 045	Classroom 110	RR	0.003		
MPES- 046	Faculty Rm 109	FL	0.004		
MPES- 047	Faculty Rm 109	FL	0.005	Spigot	
MPES- 048	Faculty Rm 109	FL	0.012		
MPES- 049	Principal Off. Rm 108	RR	0.004		
MPES- 050	Nurse's Off. Rm 140	NO	0.007		
MPES- 051	Nurse's Off. Rm 140	NO	0.003	EW	
MPES- 052	Nurse's Off. Rm 140	NO	0.007		
MPES- 053	Men's Faculty BR	RR	0.003		
MPES- 054	Men's Faculty BR	RR	< 0.001		
MPES- 055	Men's Faculty BR	IS	0.937		E
MPES- 056	Women's Faculty BR	RR	0.003		

MPES- 057	Women's Faculty BR	RR	< 0.001		
MPES- 058	Women's Faculty BR	IS	11.400		E
MPES- 059	Boy's Bathroom 162	RR	0.004		
MPES- 060	Boy's Bathroom 162	RR	0.002		
MPES- 061	Boy's Bathroom 162	RR	0.001		
MPES- 062	Boy's Bathroom 162	IS	0.296		E
MPES- 063	Classroom 183	CS	0.040		E
MPES- 064	Classroom 183	WF	0.010		
MPES- 065	Classroom 182	CS	0.007		
MPES- 066	Classroom 182	WF	0.005		
MPES- 067	Classroom 184	CS	0.024		E
MPES- 068	Classroom 184	WF	0.007		
MPES- 069	Classroom 181	CS	0.004		
MPES- 070	Classroom 181	WF	0.003		
MPES- 071	Classroom 185	CS	0.007		
MPES- 072	Classroom 185	WF	0.004		
MPES- 073	Classroom 180	CS	0.008		
MPES- 074	Classroom 180	WF	0.004		
MPES- 075	Classroom 186	CS	0.012		
MPES- 076	Classroom 186	WF	0.004		
MPES- 077	Classroom 179	CS	0.008		
MPES- 078	Classroom 179	WF	0.005		

MPES- 079	Classroom 187	CS	0.011		
MPES- 080	Classroom 187	WF	0.015	Leaking	E
MPES- 81	Classroom 178	CS	0.008		
MPES- 82	Classroom 178	WF	0.005		
MPES- 83	Classroom 189	CS	0.011	Leaky	
MPES- 84	Classroom 189	WF	0.013		
MPES- 85	Boy's Bathroom	IS	< 0.002		
MPES- 86	Girl's Bathroom	IS	0.002		
MPES- 87		SS		Does not work	
MPES- 88	Classroom 190	CS	0.003		
MPES- 89	Classroom 190	WF	0.003		
MPES- 90	Classroom 173	CS	0.018		E
MPES- 91	Classroom 173	WF	0.007		
MPES- 92	Classroom 172	CS	0.023		E
MPES- 93	Classroom 172	WF	0.012		
MPES- 94	Can Wash Room	SS	0.007		
MPES- 95	Can Wash Room	EW	0.52		E
MPES- 96	Boiler Room	BO	< 0.001		
MPES- 97	Kitchen Rm 197	KS	0.003		
MPES- 98	Kitchen Rm 197	KS	0.005		
MPES- 99	Kitchen Rm 197	KS	0.017		E
MPES- 100	Kitchen Rm 197	Kettle	0.100		E

MPES- 101	Kitchen Rm 197	KS	0.009		
MPES- 102	Kitchen Rm 197	KS	0.008		
MPES- 103	Kitchen Rm 197	KS	0.005		
MPES- 104	Music Rm 165	CS	0.007		
MPES- 105	Music Rm 165	WF	0.012		
MPES- 106	Classroom 160	CS	0.008		
MPES- 107	Classroom 160	WF	0.004		
MPES- 108	Classroom 149	CS	0.004		
MPES- 109	Classroom 149	WF	0.003		
MPES- 110	Classroom 159	CS	0.006		
MPES- 111	Classroom 159	WF	0.002		
MPES- 112	Classroom 150	CS	0.007		
MPES- 113	Classroom 150	WF	0.006		
MPES- 114	Classroom 157	CS	0.018		E
MPES- 115	Classroom 157	WF	Does not work		
MPES- 116	Gym Bathroom	Coach office	0.007		
MPES- 117	Girl's Bathroom 163	RR	< 0.001		
MPES- 118	Girl's Bathroom 163	RR	0.002		
MPES- 119	Gir's Bathroom 163	RR	0.004		
MPES- 120	Girl's Bathroom 163	IS	0.489		E
MPES- 121	Library Rm 146	Library	0.009		
MPES- 122	Classroom 136	CS	0.012		

MPES- 123	Classroom 136	WF	< 0.001		
MPES- 124	Classroom 136	RR	0.003		
MPES- 125	Classroom 148	CS	0.013		
MPES- 126	Classroom 148	WF	0.002		
MPES- 127	Cafeteria	WF	< 0.001		
MPES- 128	Janitor Closet Rm 161	SS	0.001		
MPES- 129	Hallway OS Gym Doors	WF	0.002		

General Comments:

Fixtures 005, 008, 009, 087, and 115 do not work and in turn could not be tested. This was reported to the faculty member on site on 9/16/16 when the functionality of the fixtures were tested.