

Eventus Construction Company Inc.

Cemco Water & Wastewater Specialists Inc.

District: Carmel Central School District

Location: Kent Elementary Elementary School

KEY:

| | |
|---------------------------|--------------------|
| Type of Outlet: | WF= Water Fountain |
| NO= Nurse Office | KS= Kitchen Sink |
| FL= Faculty Lounge | CS= Classroom Sink |
| BO= Boiler Room | OS= Outside Spigot |
| RR= Restroom Sink | EW= Eye Wash |
| SS= Slop Sink | FS= Floor Spigot |
| E= Exceed Allowable Limit | |

| | |
|-------|---------------|
| Draw: | |
| Date: | 9/17/2016 |
| Time: | 7:30-11:00 AM |

| Sample ID | Location | Type of Outlet | Lead Concentration | Notes Required | E |
|-----------|-------------------------|----------------|--------------------|--------------------|---|
| KES- 001 | Outside Rm 117 | OS | 0.002 | Tag on faucet pipe | |
| KES- 002 | Outside Rm 304 | OS | 0.004 | | |
| KES- 003 | Outside Rm 110 | OS | 0.078 | | E |
| KES- 004 | Principal's Off. Rm 104 | CS | 0.009 | | |
| KES- 005 | Classroom 106 | CS | 0.004 | | |
| KES- 006 | Classroom 106 | CS | 0.006 | | |
| KES- 007 | Classroom 108 | CS | 0.004 | | |
| KES- 008 | Classroom 108 | WF | < 0.001 | | |
| KES- 009 | Classroom 108 | CS | 0.004 | | |
| KES- 010 | Classroom 106 | WF | < 0.001 | | |
| KES- 011 | Classroom 110 | CS | 0.009 | | |
| KES- 012 | Classroom 110 | WF | < 0.001 | | |
| KES- 013 | Classroom 110 | CS | 0.004 | | |

| | | | | | |
|----------|-----------------------|----|---------|--|--|
| KES- 014 | Classroom 112 | CS | 0.001 | | |
| KES- 015 | Classroom 112 | WF | < 0.001 | | |
| KES- 016 | Classroom 112 | CS | 0.007 | | |
| KES- 017 | Classroom 113 | CS | 0.003 | | |
| KES- 018 | Classroom 113 | WF | 0.001 | | |
| KES- 019 | Classroom 113 | CS | 0.007 | | |
| KES- 020 | Hallway Outside Rm115 | WF | 0.003 | | |
| KES- 021 | Classroom 115 | CS | 0.006 | | |
| KES- 022 | Classroom 115 | WF | < 0.001 | | |
| KES- 023 | Classroom 115 | CS | 0.006 | | |
| KES- 024 | Classroom 119 | CS | 0.006 | | |
| KES- 025 | Classroom 119 | WF | < 0.001 | | |
| KES- 026 | Classroom 119 | CS | 0.006 | | |
| KES- 027 | Classroom 117 | WF | < 0.001 | | |
| KES- 028 | Classroom 117 | CS | 0.006 | | |
| KES- 029 | Classroom 117 | CS | 0.002 | | |
| KES- 030 | Hallway Outside Rm123 | WF | < 0.001 | | |
| KES- 031 | Nurse's Bathroom | CS | 0.001 | | |
| KES- 032 | Nurse's Bathroom | EW | < 0.001 | | |
| KES- 033 | Hallway Outside Rm227 | WF | 0.005 | | |
| KES- 034 | Kitchen Rm 240 | KS | 0.006 | | |
| KES- 035 | Kitchen Rm 240 | KS | 0.004 | | |

| | | | | | |
|----------|-----------------------|----|---------------|---------------------------|---|
| KES- 036 | Speech Room | CS | 0.010 | | |
| KES- 037 | Kitchen Rm 240 | EW | 0.026 | | E |
| KES- 038 | Kitchen Rm 240 | KS | 0.002 | | |
| KES- 039 | Kitchen Rm 240 | KS | 0.008 | | |
| KES- 040 | Kitchen Rm 240 | KS | 0.023 | | E |
| KES- 041 | Kitchen Rm 240 | KS | 0.005 | | |
| KES- 042 | Kitchen Rm 240 | KS | 0.007 | Label on front bottom | |
| KES- 043 | Kitchen Rm 240 | KS | 0.021 | | E |
| KES- 044 | Kitchen Rm 240 | KS | 0.003 | | |
| KES- 045 | Kitchen Rm 240 | KS | 0.170 | Spigot- label behind knon | E |
| KES- 046 | Kitchen Rm 240 | KS | < 0.001 | Spigot | |
| KES- 047 | Kitchen Rm 240 | KS | 0.002 | Spigot | |
| KES- 048 | Room 227 | CS | 0.006 | | |
| KES- 049 | Custodial Off. Rm 229 | SS | < 0.001 | Custodian office | |
| KES- 050 | Coach's Office | FL | 0.006 | Gym office | |
| KES- 051 | Faculty Bathroom | CS | 0.005 | | |
| KES- 052 | | WF | Does not work | | |
| KES- 053 | Faculty Rm 329 | FL | 0.006 | | |
| KES- 054 | Reading Room 234 | CS | 0.004 | | |
| KES- 055 | Girl's Bathroom | RR | 0.004 | | |
| KES- 056 | Girl's Bathroom | RR | 0.002 | | |
| KES- 057 | Girl's Bathroom | RR | 0.005 | | |

| | | | | | |
|----------|------------------|----|---------------|--|---|
| KES- 058 | Boy's Bathroom | RR | 0.005 | | |
| KES- 059 | Custodial Closet | SS | 0.048 | | E |
| KES- 060 | Kitchen Rm 240 | KS | 0.006 | | |
| KES- 061 | Classroom 331 | WF | 0.001 | | |
| KES- 062 | Classroom 331 | CS | 0.004 | | |
| KES- 063 | Classroom 331 | CS | 0.011 | | |
| KES- 064 | Classroom 333 | CS | 0.005 | | |
| KES- 065 | Classroom 333 | WF | 0.003 | | |
| KES- 066 | Classroom 333 | CS | 0.005 | | |
| KES- 067 | | WF | Does not work | | |
| KES- 068 | Custodial Closet | SS | 0.004 | | |
| KES- 069 | Classroom 304 | CS | 0.097 | | E |
| KES- 070 | Classroom 304 | WF | 0.180 | | E |
| KES- 071 | Classroom 304 | CS | 0.035 | | E |
| KES- 072 | Classroom 302 | CS | 0.018 | | E |
| KES- 073 | Classroom 302 | WF | < 0.001 | | |
| KES- 074 | Classroom 302 | CS | 0.007 | | |
| KES- 075 | Classroom 337 | WF | 0.001 | | |
| KES- 076 | Classroom 337 | CS | 0.005 | | |
| KES- 077 | Classroom 337 | CS | 0.008 | | |
| KES- 078 | Classroom 335 | CS | 0.011 | | |
| KES- 079 | Classroom 335 | WF | 0.005 | | |

| | | | | | |
|----------|-----------------------|----|---------|----------|---|
| KES- 080 | Classroom 335 | CS | 0.005 | | |
| KES- 081 | Men's Bathroom | RR | < 0.001 | | |
| KES- 082 | Hallway Outside Rm325 | WF | 0.004 | | |
| KES- 083 | Boy's Bathroom | RR | 0.001 | | |
| KES- 084 | Boy's Bathroom | RR | 0.003 | | |
| KES- 085 | Classroom 308 | WF | 0.002 | | |
| KES- 086 | Classroom 308 | CS | 0.005 | | |
| KES- 087 | Classroom 310 | WF | < 0.001 | | |
| KES- 088 | Classroom 310 | CS | 0.003 | | |
| KES- 089 | Classroom 312 | WF | 0.001 | | |
| KES- 090 | Classroom 312 | CS | 0.006 | | |
| KES- 091 | Classroom 321 | WF | < 0.001 | | |
| KES- 092 | Classroom 321 | CS | 0.005 | | |
| KES- 093 | Classroom 323 | WF | 0.002 | | |
| KES- 094 | Classroom 323 | CS | 0.007 | | |
| KES- 095 | Classroom 325 | WF | 0.001 | | |
| KES- 096 | Classroom 325 | CS | 0.004 | | |
| KES- 097 | Women's Bathroom | RR | 0.003 | | |
| KES- 098 | Women's Bathroom | RR | 0.003 | | |
| KES- 099 | Art Classroom 329 | WF | < 0.001 | | |
| KES- 100 | Art Classroom 329 | CS | < 0.001 | | |
| KES- 101 | Outside Boiler Rm | IS | 0.110 | Basement | E |

| | | | | | |
|----------|----------------------|----|-------|------------------|---|
| KES- 102 | Bathroom in Basement | FL | 0.003 | Custodian office | |
| KES- 103 | Shower in Basement | FL | 0.073 | Custodian office | E |
| KES- 104 | Custodial Closet | SS | 0.026 | | E |

Eventus Construction Company Inc.

Cemco Water & Wastewater Specialists Inc.

District: Carmel Central School District

Location: Kent Elementary Elementary School

General Comments:

Fixtures 052 and 067 do not work and in turn were unable to be sampled. These fixtures were reported not working to the Carmel CSD personnel on 9/16/16 at the time of the assesment.

Sample 058 was drawn twice. Both samples did NOT exceed the allowable limit.